

Project Release Bulletin

Project Name:	Elastix 2.4 based software images for Xorcom PBX	Date:	10-Dec-2015
PID:	XR1-xx, XR2xxx, XE2xxx, XR3xxx, XE3xxx, TS2000, TS3000	Number of Pages:	22

1. **Hardware Description**

N/A

2. **Software Description**

Name	Version	Notes
Elastix	2.4.0-11	
FreePBX	2.8.1-17	
CentOS	5.10	
Kernel	2.6.18-371.4.1.el5	
DAHDI	2.10.2-1	changed
Asterisk	11.7.0-1	
TwinStar Add-on	1.16-0	changed
Xtdmon	1.3.0	changed

3. **Bug Fixes**

- When an external USB hard disk is connected to an XE2000/3000 or TS2000/3000 PBX then this disk is automatically attached to the RAID1 array. Fixed.

4. **Changes**

- The DAHDI package has been upgraded to v.2.10.2 in order to provide support for the Astribank e-main card revision 5.7.0 (device ID 2.03).
- Minor improvements have been made to the TwinStar configuration scripts.

Table of Xorcom Rapid Recovery Images

Image Name	PBX Model
X123-SB21-2015-Dec-10	<p>The following models that have a single hard disk:</p> <ul style="list-style-type: none"> • XR1000, ITX-M42X61E and D201GLY motherboard models • XR2000, Intel D2500, D525MW and D201GLY motherboard models • XR3000, Intel S1200KP, DG41 and DG31 motherboard models
X23-RAID1-SB21-2015-Dec-10	<p>The following models that have RAID1 disks:</p> <ul style="list-style-type: none"> • XE2000, Intel D2500, D525MW and D201GLY motherboard models • XE3000, Intel S1200KP, DG41 and DG31 motherboard models
TW-X23-RAID1-SB21-2015-Dec-10	<p>The following TwinStar models that have RAID1 disks:</p> <ul style="list-style-type: none"> • XE2000, Intel D2500, D525MW and D201GLY motherboard models • XE3000, Intel S1200KP, DG41 and DG31 motherboard models

5. **Known problems**

N/A

	Name	Signature	Date	Notes
QA	Eyal Oren	Eyal Oren	9-Dec-2015	
Manufacturing Manager	Lena German	Lena German	9-Dec-2015	
Technical Support Manager	Eyal Oren	Eyal Oren	9-Dec-2015	
Marketing Manager	Ruth Bridger	Ruth	13-Dec-2015	
CTO	Leonid Fainshtein	Leonid	9-Dec-2015	
CEO	Eran Gal	Eran	3-Dec-2015	