

Project Release Bulletin

Project Name:	CompletePBX, v.03.0.05	Date:	13-Aug-2013
PID:	CXR1000, CXR2000, CXR3000, CXE2000, CXE3000, CTS2000, CTS3000,	Number of Pages:	1

Hardware Description

Part Name	CXR1000	CXR2000/CXE2000/CTS2000	CXR3000/CXE3000/CTS3000
PC Motherboard	ITX-M42X61E	D2500HN	S1200KP
CPU	Intel Atom D425 1.8 GHz	Intel Atom D2500 1.8 GHz	Intel G850, Q9550 (CXR) i3-2120, G850 (CXE/CTS)
RAM	DDR3, 2 GB	DDR3, 2GB	DDR3, 4 GB (2 GB for CXR)
Hard Disk	SSD 16 GB	SATA 250 GB	SATA 250 GB
RAID-1	N/A	Included in CXE/CTS only	Included in CXE/CTS only

Software Description

Name	Version	Notes
CentOS/Kernel	6.2/2.6.32-220.13.1.el6	
FreePBX Distro	2.210.62-7	
FreePBX	2.10	
Asterisk	1.8.20.1-34	

libpri	1.4.12-8	
xr2-panel (LCD panel software)	1.9-1	
freepbx-module-zapauto	0.7.10-1	
twinstar_addon	1.08-0	Changed
Switchboard	FOP 2.27.1	Changed
ccStats Lite (Statistics Reporting)	1.4	
ccStats Pro (Statistics Reporting)	2.0.4	Changed

Bug Fixes

- Call Center Statistics Module - Pro (ccStatsPro) didn't work properly in the TwinStar environment. Fixed.
- Icon text on the launch pad was not aligned properly. Fixed.
- Xorcom logo on the Switchboard login dialog was blurry. Fixed.

Changes

- New Switchboard (FOP2 version 2.2.7.1) has been integrated. The licensing mechanism of this version has been changed. Now, when a Xorcom USB device (e.g., an Astribank, LCD panel, etc.) is connected, the license is no longer bound to the IP address/host name of the PBX.
- New Call Center Statistics Module - Pro (ccStatsPro version 2.0.4) has been integrated. The licensing mechanism of this version has been changed. Now, when a Xorcom USB device (e.g., an Astribank, LCD panel, etc.) is connected, the license is no longer bound to the IP address/host name of the PBX.
- The Sysadmin Pro FreePBX module is no longer installed by default.
- The Outbound Call Limiting (Outbound Call Limit FreePBX) module is no longer installed by default on CXE2000, CXE3000, CTS2000 and CTS3000 appliances.
- The Fax Master (Outbound Fax FreePBX) module is no longer installed by default on CXE2000, CXE3000, CTS2000 and CTS3000 appliances.

Table of Xorcom Rapid Recovery Images

Image Name	Server Model
CPBX-03.0.05-X123	CXR1000 (Celeron and Atom D425 CPU based), CXR2000 (Celeron, D525 and D2500 CPU based), CXR3000 (G850, E8400, Q9550 CPU based)
CPBX-03.0.05-X23-RAID1	CXE2000 (Celeron, D525 and D2500 CPU based), CXE3000 (Q9550 and i3-2120 CPU based)
CPBX-03.0.05-X23-RAID1-TW	CTS2000 (Celeron, D525 and D2500 CPU based), CTS3000 (Q9550 and i3-2120 CPU based)

	Name	Signature	Date	Notes
QA	Aslan Laoz			
Manufacturing Manager	Lena German			
Technical Support Manager	Dennis Buteyn			
Marketing Manager	Ruth Bridger			
CTO	Leonid Fainshtein			
CEO	Eran Gal			