



Project Release Bulletin

Project Name:	CompletePBX v.4.5.2	Date:	20-Oct-2014
PID:	CX1-xx, CXR2xxx, CXE2xxx, CXR3xxx, CXE3xxx, CXT3xxx, CXE4000, CTS2000, CTS3000, CXTS3000, CTS4000	Number of Pages:	2

1. Overview

This is a maintenance release that provides some bug fixes in the System Settings and Fax Master modules.

2. Software Description

Name	Version	Notes
CentOS/Kernel	6.5/2.6.32-431.29.2.el6	Changed
FreePBX	2.11	
Asterisk	11.13.1	Changed
DAHDI	2.10.0-1	
libpri	1.4.14-2	
xr2-panel (LCD panel software)	2.1.6-1	
freepbx-module-zapauto	0.7.14-1	
twinstar_addon	1.14-0	
Switchboard	FOP 2.27.2	
ccStats Lite (Statistics Reporting)	1.5	
ccStats Pro (Statistics Reporting)	2.0.5	

3. **Resolved Issues**

- It is now possible to send a fax via the My Extension Web interface.
- It is now possible to change the Web interface language in My Extension.
- It is now possible to apply the network settings changes on the System Settings|Network Settings dialog when multiple DNS server addresses are separated by space.
- The Power Options item appears now in the System Settings menu.
- The fail2ban log file is defined now in the Asterisk logging settings.
- It is now possible to define line buttons for the Yealink T4x phones in EndpointManager. This fix requires an update of the Endpoint Manager module to v. 1.0.11. Use the following command: **yum update cpbx-xepm**

4. **Changes**

- Asterisk has been upgraded to v.11.13.1. This is a security release. For further details please see the Asterisk change log:
<http://downloads.asterisk.org/pub/telephony/asterisk/releases/ChangeLog-11.13.1>

Table of Xorcom Rapid Recovery Images

Image Name	Server Model
CPBX-4.5.2-X123	CXR1000 (Celeron and Atom D425 CPU based), CXR2000 (Celeron, D525 and D2500 CPU based), CXR3000 (G850, E8400, Q9550 CPU based)
CPBX-4.5.2-X23-RAID1	CXE2000 (Celeron, D525 and D2500 CPU based), CXE3000/CXT3000 (Q9550 and i3-2120 CPU based)
CPBX-4.5.2-X23-RAID1-TW	CTS2000 (Celeron, D525 and D2500 CPU based), CTS3000/CXTS3000 (Q9550 and i3-2120 CPU based)
CPBX-4.5.2-X4-TW	CTS4000
CPBX-4.5.2-X4	CXE4000